

Maschinenschrauben Linsenkopf

Kreuzschlitz PH DIN 7985

Edelstahl A2

Größe	Steigung	Bit	Kopfhöhe	Kopfdurchmesser	Kernlochbohrer	Durchgangsloch (mittel)	Längen
M2	0,4	PH1	1,6	4	1,6	2,4	3, 4, 5, 6, 8, 10, 12, 14, 16, 18, 20
M2,5	0,45	PH1	2	5	2,05	2,9	4, 5, 6, 8, 10, 12, 14, 16, 18, 20, 25
M3	0,5				2,5	3,4	4, 5, 6, 8, 10, 12, 14, 16, 18, 20, 22, 25, 28, 30, 35
M4	0,7				3,3	4,5	4, 5, 6, 8, 10, 12, 14, 16, 18, 20, 22, 25, 28, 30, 35, 40, 45, 50, 55, 60, 70
M5	0,8				4,2	5,5	6, 8, 10, 12, 14, 15, 16, 18, 20, 22, 25, 30, 35, 40, 45, 50
M6	1				5	6,6	8, 9, 10, 12, 14, 16, 18, 20, 22, 25, 30, 35, 40, 45, 50

Maße in mm. Nennmaße; die Toleranzen stehen in der Norm.