

## Set screws hex socket, flat point ISO 4026

45H zinc-plated

| Size       | Pitch | Hex key | Lengths                                                   |
|------------|-------|---------|-----------------------------------------------------------|
| <b>M2</b>  | 0.4   | 0.9     | 5, 6, 8                                                   |
| <b>M3</b>  | 0.5   | 1.5     | 3, 4, 5, 6, 8, 10, 12, 16, 20                             |
| <b>M4</b>  | 0.7   | 2       | 4, 5, 6, 8, 10, 12, 16, 20, 25                            |
| <b>M5</b>  | 0.8   | 2.5     | 5, 6, 8, 10, 12, 16, 20, 25, 30, 35                       |
| <b>M6</b>  | 1     | 3       | 4, 6, 8, 10, 12, 16, 20, 25, 30, 35, 40, 45, 50           |
| <b>M8</b>  | 1.25  | 4       | 8, 10, 12, 16, 20, 25, 30, 35, 40, 45, 50, 55, 60, 65, 70 |
| <b>M10</b> | 1.5   | 5       | 10, 12, 14, 16, 20, 25, 30, 35, 40, 45, 50, 60, 70, 80    |
| <b>M12</b> | 1.75  | 6       | 12, 16, 20, 25, 30, 35, 40, 45, 50, 60, 70, 80            |
| <b>M16</b> | 2     | 8       | 16, 20, 25, 30, 35, 40, 50, 55, 60, 70, 80, 90, 100       |

Dimensions in mm. Nominal sizes; tolerances are given in the standard.